Vlad's Autobahn LLC

354 West Drive Melbourne, FL 32904 +1 3216225665 vladsautobahn@gmail.com



Estimate

ADDRESS

Robert Skelton 2859 School Drive NE Palm Bay, FL 32905 931-307-9722 **ESTIMATE #** 9981 **DATE** 06/06/2022

MAKE/ MODEL/ YEAR Ferrari 360 Spider 2001 VEHICLE ID #

MILEAGE IN/ MILEAGE OUT

ZFFYT53A310125573

| ITEM | DESCRIPTION | QTY | RATE | AMOUNT |
|---------|--|------|----------|-----------|
| Service | Coolant Service | 1 | 295.00 | 295.00T |
| Service | Clamps | 10 | 5.00 | 50.00T |
| Labor | Install Clamps | 1 | 180.00 | 180.00T |
| Service | Hi Flow Air Filter Set | 1 | 315.00 | 315.00T |
| Service | Engine Oil Filter | 1 | 34.71 | 34.71T |
| Service | Drain Plug Seal | 1 | 6.00 | 6.00T |
| Service | Engine Oil | 13 | 12.00 | 156.00T |
| Labor | Perform Engine Oil Service | 1 | 180.00 | 180.00T |
| Service | Tank Hoses and Clamps Set | 1 | 105.00 | 105.00T |
| Service | Oil Tank Gasket | 1 | 0.00 | 0.00T |
| Service | O-Ring between engine and transmission | 5 | 3.97 | 19.85T |
| Service | Crush Washers (oil cooler lines at trans.) | 1 | 0.00 | 0.00T |
| Service | Low Pressure P/S Return | 1 | 135.00 | 135.00T |
| Service | P/S Fluid | 6 | 45.00 | 270.00T |
| Service | Power Steering Line | 1 | 177.00 | 177.00T |
| Labor | Replace Power Steering Lines | 4 | 180.00 | 720.00T |
| Service | Transmission Bushing | 1 | 155.00 | 155.00T |
| Service | Transmission Torque Mount | 1 | 202.67 | 202.67T |
| Service | Engine Mounts | 2 | 166.98 | 333.96T |
| Labor | Replace Engine and Transmission Mounts | 2.50 | 180.00 | 450.00T |
| Service | Clutch Kit | 1 | 1,748.44 | 1,748.44T |
| Service | FlyWheel | 1 | 962.78 | 962.78T |
| Service | Pressure Plate Bolts | 8 | 4.00 | 32.00T |
| Service | Flywheel Bolts | 8 | 3.00 | 24.00T |
| | | | | |

| ITEM | DESCRIPTION | QTY | RATE | AMOUNT |
|---------|---|------|----------|-----------|
| Service | Throw Out Bearing HE* | 1 | 468.00 | 468.00T |
| Service | Bearing Mount Flange HE* | 1 | 435.00 | 435.00T |
| Service | Rear Main Seal | 1 | 42.00 | 42.00T |
| Service | Pilot Bearing | 1 | 36.00 | 36.00T |
| Labor | Replace Clutch | 15 | 180.00 | 2,700.00T |
| Service | Timing Belts | 2 | 120.00 | 240.00T |
| Service | Timing Belt Pulleys | 2 | 210.00 | 420.00T |
| Service | Timing Belt Tensioners HE* | 2 | 170.00 | 340.00T |
| Labor | Replace Timing Belt | 7 | 180.00 | 1,260.00T |
| Service | Inspection Cover and Hardware | 1 | 185.00 | 185.00T |
| Service | Steering Rack | 1 | 5,588.00 | 5,588.00T |
| Service | Outer Tie Rod Ends | 2 | 543.84 | 1,087.68T |
| Labor | Replace Steering Rack | 5 | 180.00 | 900.00T |
| Service | Perform Alignment | 1 | 390.00 | 390.00T |
| Service | Convertible Top Seal Kits | 1 | 250.00 | 250.00T |
| Labor | Repair Convertible Top Leaks and Repair Top | 8 | 180.00 | 1,440.00T |
| Service | Hydraulic Fluid | 2 | 20.00 | 40.00T |
| Service | Throttle Body O-Rings | 2 | 15.00 | 30.00T |
| Labor | Clean Engine and Transmission | 2.50 | 180.00 | 450.00T |
| Service | Cleaning Supplies | 1 | 55.00 | 55.00T |
| Service | Shipping / Handling Charges | 1 | 2,280.00 | 2,280.00T |

Estimates are good for 30 days. There is a minimum fee of 1 hour labor (\$180.00) for all diagnostic work. Not responsible for damage caused by theft, fire or acts of nature. I hereby authorize the above repairs, including sublet work, along with necessary materials. You and your employees may operate my vehicle for the purpose of testing, inspection and delivery at my risk. If I cancel repairs prior to their completion for any reason, a tear down and reassembly fee of \$______ will be applied. After 3 days there will be a charge of \$35/day for storage, if we do not receive job authorization or completion of repairs. There will an additional 3.25% fee for processing credit/debit card charges.

 SUBTOTAL
 25,189.09

 TAX
 1,757.37

 TOTAL
 \$26,946.46

Accepted By

Accepted Date