

Vlad's Autobahn LLC
 354 West Drive
 Melbourne, FL 32904
 +1 3216225665
 vladsautobahn@gmail.com



Estimate

ADDRESS

Robert Skelton
 2859 School Drive NE
 Palm Bay, FL 32905
 931-307-9722

ESTIMATE # 9981
 DATE 06/06/2022

MAKE/ MODEL/ YEAR	VEHICLE ID #	MILEAGE IN/ MILEAGE OUT
Ferrari 360 Spider 2001	ZFFYT53A310125573	*

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
Service	Rear Under Panel	1	930.02	930.02T
Service	Coolant Service	1	295.00	295.00T
Service	Clamps	10	5.00	50.00T
Labor	Install Clamps	1	180.00	180.00T
Service	Hi Flow Air Filter Set	1	315.00	315.00T
Service	Engine Oil Filter	1	34.71	34.71T
Service	Drain Plug Seal	1	6.00	6.00T
Service	Engine Oil	13	12.00	156.00T
Labor	Perform Engine Oil Service	1	180.00	180.00T
Service	Tank Hoses and Clamps Set	1	105.00	105.00T
Service	Oil Tank Gasket	1	0.00	0.00T
Service	O-Ring between engine and transmission	5	3.97	19.85T
Service	Crush Washers (oil cooler lines at trans.)	1	0.00	0.00T
Service	Low Pressure P/S Return	1	135.00	135.00T
Service	P/S Fluid	6	45.00	270.00T
Service	Power Steering Line	1	177.00	177.00T
Labor	Replace Power Steering Lines	4	180.00	720.00T
Service	Transmission Bushing	1	155.00	155.00T
Service	Transmission Torque Mount	1	202.67	202.67T
Service	Engine Mounts	2	166.98	333.96T
Labor	Replace Engine and Transmission Mounts	2.50	180.00	450.00T
Service	Clutch Kit	1	1,748.44	1,748.44T
Service	FlyWheel	1	962.78	962.78T
Service	Pressure Plate Bolts	8	4.00	32.00T

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
Service	Flywheel Bolts	8	3.00	24.00T
Service	Throw Out Bearing HE*	1	468.00	468.00T
Service	Bearing Mount Flange HE*	1	435.00	435.00T
Service	Rear Main Seal	1	42.00	42.00T
Service	Pilot Bearing	1	36.00	36.00T
Labor	Replace Clutch	15	180.00	2,700.00T
Service	Timing Belts	2	120.00	240.00T
Service	Timing Belt Pulleys	2	210.00	420.00T
Service	Timing Belt Tensioners HE*	2	170.00	340.00T
Labor	Replace Timing Belt	7	180.00	1,260.00T
Service	Inspection Cover and Hardware	1	185.00	185.00T
Service	Steering Rack	1	5,588.00	5,588.00T
Service	Outer Tie Rod Ends	2	543.84	1,087.68T
Labor	Replace Steering Rack	5	180.00	900.00T
Service	Perform Alignment	1	390.00	390.00T
Service	Convertible Top Seal Kits	1	250.00	250.00T
Labor	Repair Convertible Top Leaks and Repair Top	8	180.00	1,440.00T
Service	Hydraulic Fluid	2	20.00	40.00T
Service	Throttle Body O-Rings	2	15.00	30.00T
Labor	Clean Engine and Transmission	2.50	180.00	450.00T
Service	Cleaning Supplies	1	55.00	55.00T
Service	Shipping / Handling Charges	1	2,280.00	2,280.00T

Estimates are good for 30 days. There is a minimum fee of 1 hour labor (\$180.00) for all diagnostic work. Not responsible for damage caused by theft, fire or acts of nature. I hereby authorize the above repairs, including sublet work, along with necessary materials. You and your employees may operate my vehicle for the purpose of testing, inspection and delivery at my risk. If I cancel repairs prior to their completion for any reason, a tear down and reassembly fee of \$ _____ will be applied. After 3 days there will be a charge of \$35/day for storage, if we do not receive job authorization or completion of repairs. There will an additional 3.25% fee for processing credit/debit card charges.

SUBTOTAL	26,119.11
TAX	1,822.47
TOTAL	\$27,941.58

Accepted By

Accepted Date